

ANACONDA Copper Company


New Mexico Operations
P.O. Box 638
Grants, New Mexico 87020
505/876-2211



dcj
10/8
mn

June 7, 1979

A. F. Czarnowsky
Area Mining Supervisor
United States Geological Survey
P. O. Box 26124
Albuquerque, N.M. 87125



Dear Mr. Czarnowsky:

The following information is being submitted in accordance with the Jackpile Mine Reclamation Sampling Plan.

1. Radiological and chemical analysis of reclamation site soils.
2. Surface gamma emission from reclaimed sites.
3. Radon exhalation values from reclaimed sites.

Christopher Sanchez
Reclamation Engineer

cc: RDL
MAS
ECL
EAL
file